

ENTIRE FACILITY REFERRAL DOCUMENTATION
RCRA CA Deferral to SUPERFUND
Region 1 - New England

RCRA RECORDS CENTER
FACILITY: Fiber Materials
I.D. NO. MED048268890
FILE LOC: R-5
OTHER: _____

The facility known as FIBER MATERIALS INC., EPA ID#MED048268890, located at 5 Morin Street in Biddeford, ME, is or was, a facility subject to RCRA Corrective Action (CA).

However, the Region 1 RCRA CA and Superfund programs have determined it is most advantageous that the remedial actions at this facility be addressed under the Superfund program. Because the Superfund program has taken responsibility for the cleanup of this facility, the Superfund program will be tracking the remedial actions under their (e.g., GPRA) measures, and the facility will no longer be tracked on the RCRA CA Program's GPRA Baseline or measures.

Comments:

This facility was listed in the Office of Inspector General (OIG) 1999 audit report "Superfund Sites Deferred to RCRA", EISFF8-11-0006-9100116. This facility was identified during the audit as (please indicate):

- ~~1. Potentially not being part of the RCRA CA universe~~
- ~~2. Not being found in the RCRA CA universe~~
- 3. Being subject to RCRA CA but not statutorily required to be addressed by the RCRA program

Needed Actions: UNDEFER & UNARCHIVE, change qualifier to LOW

Assign SI to contractor or state


Change address from "A Street Biddeford Ind. Park" to "5 Morin Street"

CERCLIS Status

Last CERCLIS entry is a Preliminary Assessment, 09-30-92, current qualifier is NFRAP, archived

Don Smith
EPA Superfund Site Assessment Manager

8-22-00
Date



RCRIS Status

David Lin
EPA RCRA Facility Manager

9/5/00
Date

EPA Section Chief Approval

Dennis R. Segur
Chief, Technical Support & Site Assessment

9/28/00
Date

Mark S. England
Chief, RCRA Corrective Action

9/25/00
Date

EPA Branch Chief Approval

Stanley D. Ch...
Chief, Technical & Support Branch

9/3/00
Date

DF
Chief, Restoration & Remediation II

10/4/00
Date